

# TESLA SERVICE STATION FIRE CRAWLEY, UK - 2<sup>ND</sup> MARCH 2020

A significant fire broke out at a Tesla Car Service Station in Crawley, West Sussex on 2<sup>nd</sup> of March 2019. Thick black smoke and small explosions could be seen and heard from eyewitnesses.



It took more than 50 firefighters, eight fire engines and 3 hours to get the fire under control. 50% of the building was damaged due to fire, heat and smoke. Even after 3 hours four appliances remained at the scene to locate hot spots and ensure that all the fire was out.

See link below to video of the incident: <https://www.bbc.com/news/uk-england-sussex-47427311>

The fire was believed to have started in the storeroom for parts and was treated as accidental. No one was hurt or injured.



The **Bridgehill Vehicle Fire Blanket** contains smoke, fumes and heat and controls the fire within seconds. We recommend Bridgehill Fire Blankets be placed strategically throughout showrooms and workshops as part of their Fire Prevention Plan.

**NO WATER – NO FOAM – NO MESS**